

167 Technology Dr.

Irvine | CA 92618 | USA

Tel: 949-453-3990 Fax: 949-453-3995 www.lantronix.com

**Date:** 4/15/2011 **PCN No.:** 159

## PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

Lantronix is pleased to announce the release of new and improved firmware version 5.2.0.0 R21 for the XPort AR. In addition, design changes were implemented on the casing to ensure high production yields. The easy upgrade to firmware version 5.2.0.0 R21, now available at the Lantronix website, offers several new improvements, including:

TCP max retransmissions are now configurable.

Increased number of Hosts available for the CLI login menu.

DHCP to AutoIP failover.

Improved SNMP:

Adds IP configurable "IP Time To Live", to correspond to SNMP's "ipDefaultTTL". SNMP trap host configuration now accepts a hostname, not just an IP address.

Improved Web Manager: Display of XML groups now uses three columns for improved visibility.

Improved TFTP: TFTP now optionally supports XCR import.

For quality and tracking purposes, the manufacturing revision numbers on the product label will be changed. New revision numbers are also listed in the table.

		Current	New Revision With Firmware
Part Numbers	Description	Revision	5.2.0.0
XP3002000-01R	XPORT AR, EXTENDED TEMP, -40 TO 85C, RoHS	F14	G15
XP300200S-01R	XPORT AR, EXTENDED TEMP, -40 TO 85C, SAMPLE, RoHS	F15	G16

**SCHEDULE:** Please note that factory shipments with new firmware version 5.2.0.0 along with the new will approximately begin shipping on **May 13<sup>th</sup>**, **2011**.

For customers that would like to take advantage of the new capabilities immediately, the new firmware and associated release notes are available for download from our website: http://www.lantronix.com/support/downloads.html

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

