

## SLC8 Console Manager Firmware Update v2.1 Now Available

### Summary of issue:

The SLC8 v2.0 Console Manager web interface does not properly display device port information for Device Ports 4, 6 and 8, independent of whether the device port is selected from the Device Port web page or from the Device Port selector at the top of each web page. This issue does not affect the command line interface (CLI), as users are able to view and change all Device Port settings.

### Affected Products:

SLC00812N-01	SLC8: 8 Port, Single AC Supply Secure Console Manager
SLC00822N-01	SLC8: 8 Port, Dual AC Supply Secure Console Manager
SLC00824T-01	SLC8: 8 Port, Dual DC Supply Secure Console Manager

### Resolution:

A firmware update is available for the SLC8, which corrects the above issue, allowing users to properly view and change all Device Port settings web interface. It is available for download from the Lantronix ftp site at:

<ftp://ftp.lantronix.com/pub/slc8/patch/>

**Note:** Do not rename the firmware file - it must retain the same filename in order for the firmware upgrade to complete successfully.

After downloading the update, please review the associated release notes (SLC\_v2\_1relnotes.txt) for instructions on installing the update. The firmware can be updated using either the 'SLC Maintenance' web page, or with the 'admin ftp' and 'admin firmware' CLI commands.

**For more details and download information, release notes are available via the Lantronix web site ([www.lantronix.com](http://www.lantronix.com)) and via anonymous FTP from [ftp.lantronix.com](ftp://ftp.lantronix.com).**

© 2005 Lantronix, Inc. All rights reserved. Lantronix, SecureLinX and the Lantronix logo are registered trademarks of Lantronix, Inc.