

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of a new SLC-03 software maintenance release. The tables below list SLC-03 product SKUs (under Discontinued Part Number) where this new release is applicable as well as a replacement part number along with description.

For more information on the SLC-03 End-of-Life Milestones and Dates, refer to PCN-379.

Change Type

Software

Products Affected

Table 1: Affected Product Part Numbers - Single AC Power Supply Models

Discontinued Part Number	Replacement Part Number	Replacement Part Description
SLC00812N-03	SLC80081201S	SLC 8000 Advanced Console Manager - 8 Ports RJ45, Single AC Supply
SLC01612N-03	SLC80161201S	SLC 8000 Advanced Console Manager - 16 Ports RJ45, Single AC Supply
SLC03212N-03	SLC80321201S	SLC 8000 Advanced Console Manager - 32 Ports RJ45, Single AC Supply
SLC04812N-03	SLC80481201S	SLC 8000 Advanced Console Manager - 48 Ports RJ45, Single AC Supply

Table 3: Affected Product Part Numbers: Dual AC Power Supply Models

Discontinued Part Number	Replacement Part Number	Replacement Part Description
SLC00822N-03	SLC80082201S	SLC 8000 Advanced Console Manager - 8 Ports RJ45, Dual AC Supply
SLC01622N-03	SLC80162201S	SLC 8000 Advanced Console Manager - 16 Ports RJ45, Dual AC Supply
SLC03222N-03	SLC80322201S	SLC 8000 Advanced Console Manager - 32 Ports RJ45, Dual AC Supply
SLC04822N-03	SLC80482201S	SLC 8000 Advanced Console Manager - 48 Ports RJ45, Dual AC Supply

Table 4: Affected Product Part Numbers - Dual DC Power Supply Models

Discontinued Part Number	Replacement Part Number	Replacement Part Description
SLC00824N-03	No replacement available	
SLC01624N-03	SLC80162401S	SLC 8000 Advanced Console Manager - 16 Ports RJ45, Dual DC Supply
SLC03224N-03	SLC80322401S	SLC 8000 Advanced Console Manager - 32 Ports RJ45, Dual DC Supply
SLC04824N-03	SLC80482401S	SLC 8000 Advanced Console Manager - 48 Ports RJ45, Dual DC Supply

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved SLC-03 firmware version 6.3.0.0. The release includes new features and bug fixes including:

- The Java-based WebSSH and WebTelnet application has been replaced with a non-Java-based application.
- Support for Transport Layer Security (TLS) 1.1 and 1.2 has been added
- Zero Touch Provisioning – allows a SLC device to acquire a default configuration from a DHCP or TFTP server upon boot up
- Web SSL certificate is 2048 bit as a default
- NTP vulnerabilities CVE-2013-5211, CVE-2014-9293, CVE-2014-9294, CVE-2014-9295 and CVE-2014-9296 have been fixed
- SSH vulnerability CVE-2015-5600 has been fixed
- HTTP clickjacking vulnerability CVE-2016-0734 has been fixed
- Insecure DES and 3DES ciphers (CVE-2016-2183) have been removed from SSL support

For customers that would like to take advantage of the new capabilities of firmware version 6.3.0.0, the firmware patch is available for download from our website: <http://www.lantronix.com/support/downloads>.

Effect of Change on Fit, Form, or Function

Change is limited to product functionality described above.

Effective Date of Change

The firmware is available for download from our website: <http://www.lantronix.com/support/downloads>.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.