LANTRONIX®

167 Technology Dr.

Irvine **|** CA 92618 **|** USA

Tel: 949-453-3990

Fax: 949-453-3995

www.lantronix.com

Date: 7/1/15   **PCN No.:** 319

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products.

Change Type
Firmware

Products Affected

Part Number	Description	Old Revision	New Revision
SLC80081201S	SLC 8000 8-Port Advanced Console Manager, Single AC Power Supply	A12	B12
SLC80082201S	SLC 8000 8-Port Advanced Console Manager, Dual AC Power Supply	A12	B12
SLC80161201S	SLC 8000 16-Port Advanced Console Manager, Single AC Power Supply	A12	B12
SLC80162201S	SLC 8000 16-Port Advanced Console Manager, Dual AC Power Supply	A12	B12
SLC80162401S	SLC 8000 16-Port Advanced Console Manager, Dual DC Power Supply	A11	B11
SLC80321201S	SLC 8000 32-Port Advanced Console Manager, Single AC Power Supply	A12	B12
SLC80322201S	SLC 8000 32-Port Advanced Console Manager, Dual AC Power Supply	A12	B12
SLC80322401S	SLC 8000 32-Port Advanced Console Manager, Dual DC Power Supply	A11	B11
SLC80481201S	SLC 8000 48-Port Advanced Console Manager, Single AC Power Supply	A12	B12
SLC80482201S	SLC 8000 48-Port Advanced Console Manager, Dual AC Power Supply	A12	B12
SLC80482401S	SLC 8000 48-Port Advanced Console Manager, Dual DC Power Supply	A11	B11

Description and Extent of Change
Lantronix is pleased to announce the release of new and improved SLC 8000 firmware 7.2.0.0. The release includes new features and bug fixes including:

- Support for SLC 8000 USB I/O Modules
- Configurable port timeout feature per direction of traffic
- Banner message showing number of active users on device ports
- Upgraded openSSH to version 6.7
- Certified FIPS 140-2 mode

For customers that would like to take advantage of the above new capabilities, firmware will be available for download from our website on July 6, 2015: http://www.lantronix.com/support/downloads.html.

Effect of Change on Fit, Form, Function, Quality, or Reliability
Change is limited to product functionality.

Effective Date of Change
Affected products with firmware 7.2.0.0 will begin shipping from the factory on July 6, 2015.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

LANTRONIX®