# LANTRONIX®

**Date:** 12/10/2014                                      **PCN No.:** 275

# PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products. This notification is for your information.

**Change Type**

Device Firmware

**Product(s) Affected**

| Part Number | Description | Current Revision | New Revision |
|---|---|---|---|
| SLB882KIT-15P | **SLB882 Branch Office Manager** (110 VAC, 50/60 Hz), 8x Power Outlets (NEMA 5-20R), 8x Serial Ports, 2x Automatic Transfer Switching Power Inlets (IEC60320/C20), 2x Inlet Power Cords (IEC60320/C19 to NEMA 5-15P) | C16 | D16 |
| SLB882KIT-20P | **SLB882 Branch Office Manager** (110 VAC, 50/60 Hz), 8x Power Outlets (NEMA 5-20R), 8x Serial Ports, 2x Automatic Transfer Switching Power Inlets (IEC60320/C20), 2x Inlet Power Cords (IEC60320/C19 to NEMA 5-20P) | C16 | D16 |
| SLB8824KIT-AP | **SLB8824 Branch Office Manager** (220 VAC, 50/60 Hz), 8x Power Outlets (IEC60320/C13), 8x Serial Ports, 2x Automatic Transfer Switching Power Inlets (IEC60320/C20), 4x Inlet Power Cords (2x IEC60320/C19 to AS3112/AU, 2x IEC60320/C19 to China/CN) | A13 | B14 |
| SLB8824KIT-EU | **SLB8824 Branch Office Manager** (220 VAC, 50/60 Hz), 8x Power Outlets (IEC60320/C13), 8x Serial Ports, 2x Automatic Transfer Switching Power Inlets (IEC60320/C20), 4x Inlet Power Cords (2x IEC60320/C19 to Schuko/EU, 2x IEC60320/C19 to BS1363/UK) | A13 | B13 |
| SLB8824KIT-WW | **SLB8824 Branch Office Manager** (220 VAC, 50/60 Hz), 8x Power Outlets (IEC60320/C13), 8x Serial Ports, 2x Automatic Transfer Switching Power Inlets (IEC60320/C20), 4x Inlet Power Cords (1x IEC60320/C19 to Schuko/EU, 1x IEC60320/C19 to BS1363/UK, 1x IEC60320/C19 to AS3112/AU, 1x IEC60320/C19 to China/CN) | A13 | B14 |

Lantronix is pleased to announce the release of new application firmware version **6.1.0.0**.  The new firmware offers several improvements, including:

- Updated SSL version to 0.9.8q
- Support for Safari/iPad browser, and IE9 and IE10
- Updated timezones to conform to latest standards
- Direct support for Server Technology PDU
- Enhanced NTP status information
- Expanded group display on the web
- Hostname on top web banner
- Support for FAT32 on USB flash drives
- Updated online help

Refer to the release notes for a complete listing of additional features and bug fixes.

For customers that would like to take advantage of the above new capabilities, the firmware is now available for download from our website: http://www.lantronix.com/support/downloads.html

**Effect of Change on Fit, Form, Function, Quality, or Reliability**

Change is limited to product functionality.

**Effective Date of Change**
The above listed products with firmware 6.1.0.0 will begin shipping from the factory by February 2015.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721