

Document no. 900-459 Rev. C

167 Technology Drive Irvine | CA 92618 | USA Tel: 949-453-3990 Fax: 949-450-7249 www.lantronix.com

ERRATA: LED FUNCTIONALITY

Dear Valued Lantronix Customer,

There is a known issue with this product's wireless LED status light. The product functions correctly, however, the wireless LED light operates opposite of what is shown in the User Guide.

LED functionality on this unit:

Wireless off => LED on Wireless on, searching => LED on Wireless on, attempt to associate => LED blinking (very short) Wireless on, associated, power management off => LED off Wireless on, associated, power management on => LED off when receiving or transmitted, on in between.

This is an issue in the wireless radio driver, not in the design of the product. Lantronix is working with the radio manufacturer to have the problem corrected, and a firmware fix will be released at a future date.

For further information on this issue, please visit the link below and review FAQ ID 1296.

www.lantronix.com/support/

If you have questions or concerns, please contact Lantronix Technical Support at 800.422.7044 (US only), or 949.453.7198.

Best regards,

