



Irvine | CA 92618 | USA

Tel: 949-453-3990 Fax: 959-453-3995 www.lantronix.com

Date: [9 September 2008] PCN No.: [101

PRODUCT CHANGE NOTICE MatchPort® b/g

Dear Valued Lantronix Customer,

Lantronix will be the launching the updated and improved version 6.6 MatchPort b/g firmware. Effective Sept/Oct 2008, firmware version 6.6.0.0 and Web Manager version 1.7.0.0 will begin shipping on the MatchPort b/g products listed in the table below. This new firmware version offers several new features, including:

Soft AP Roaming

• SmartRoam[™] technology takes a proactive approach in transfer of connectivity from one Access Point to another Access Point belonging to the same ESS (i.e. having the same SSID or Network Name).

DNS lookup in Connect Mode

• Allows the name of a remote machine to be resolved automatically.

Expanded Monitor Mode commands 'NC' and 'co' to include name server IP address

• Shows the unit's current IP address, gateway, subnet mask, and DNS server.

In addition to the new features we have also added China RoHS and WEEE labeling to the MatchPort b/g.

For quality and tracking purposes, the manufacturing revision numbers on the product label will be changed. New revision numbers are also listed in the table.

MatchPort b/g Part Numbers	Description	Current Revision	New Revision with Firmware 6.6.0.0
MP1001000G-01	MatchPort b/g bulk pack	B15	C16
	MatchPort b/g bulk AES		
MP1002000G-01	Encryption	B15	C16
MP100200SG-01	Standard MatchPort b/g Sample Unit	B15	C16

SCHEDULE: The revised products will begin shipping Sept/Oct 2008.

PRICING: The pricing for all MatchPort b/g products will remain the same as your current pricing. If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

