

Date: 10/25/2013

PCN No.: 212

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

Lantronix is pleased to announce the release of new and improved firmware version 5.2.0.4 for the MatchPort AR Device Server. The new firmware, now available at the Lantronix website, offers several new improvements, including:

- Support for standard line speed of 110bps and custom speeds down to 110bps
- Improved XML import
- Configurable maximum retransmissions for TCP
- Improved CLI features
- Improved SDK features
- DHCP to AutoIP failover
- Modbus protocol with optional RSS Trace
- New SNMP features
- TFTP enhancements
- SSL improved

Full details of all the additions to this software update are available in the release notes.

| Part Numbers | Product Description | Current Revision | New Revision |
|---------------|---|------------------|--------------|
| MPR3002000-01 | MatchPort AR Device Server, 4MB Flash, for Evolution OS, Bulk, RoHS | D14 | E14 |
| MPR300200S-01 | MatchPort AR Device Server, 4MB Flash, for Evolution OS, Sample, RoHS | D16 | E16 |
| MPR4003000-01 | MatchPort AR Device Server, 8MB Flash, for Evolution OS, Bulk, RoHS | B12 | C12 |
| MPR400300S-01 | MatchPort AR Device Server, 8MB Flash, for Evolution OS, Sample, RoHS | B12 | C12 |

SCHEDULE: Please note that products with firmware 5.2.0.4 will begin shipping from the factory approximately by **April 30, 2014**.

For customers that would like to take advantage of the new capabilities immediately, the new firmware and associated release notes are now available for download from our website:

<http://www.lantronix.com/support/downloads.html>

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.