

Date: 7/20/2010

PCN No.: [141]

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of the immediate release of SecureLinx SLB firmware version 5.5a. Version 5.5a includes a critical bug fix that updates the boot-loader. Version 5.5a also includes an update to the SSL certificate. All SLB models listed below should have the base code of version 5.5a installed.

Part Number	Description	Current Revision	New Revision with Firmware V5.5A
SLB088411-02	Branch Office Manager, 1U, 110VAC Output (8 serial, 8 Ethernet, 4 power)	A11	B11
SLB088412-02	Branch Office Manager, 1U, 220VAC Output (8 serial, 8 Ethernet, 4 power)	A11	B11

SCHEDULE: The revised products will begin shipping immediately.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721

Product Marketing

