

167 Technology Dr.

Irvine | CA 92618 | USA

Tel: 949-453-3990 Fax: 949-453-3995 www.lantronix.com

**Date:** March 15, 2011 **PCN No.:** 154

## PRODUCT DISCONTINUATION NOTICE

Dear Valued Lantronix Customer,

The purpose of this notification is to inform you that Lantronix is discontinuing the following embedded products: Cobox Micro CO-E1-11AA, CO-E1-IAP-R, CO-E2-110AAR, CO-E2-113AAR, CO-E2-11AA, CO-E2-12AA-R; WiPort WP2001000-02, DSTni-EX LX100PEC1-02R, LX1600EC1-02R, LX160PEC1-02R LX1000000-02R, LX180000B-02, LX180000B-02R, LX2000000-02R, EX1000000-01R chips; MSSLITE-B2, MSSLITE-C, and MSSLITEX-C1.

The deadline for placing a final non-cancellable, non-returnable purchase order is <u>May 31<sup>st</sup>, 2011</u> and <u>shipments scheduled no later than August 31<sup>st</sup>,2011</u> (availability subject to supply on hand). The last day of support for this product will be <u>August 31<sup>st</sup>,2012</u>.

The table below shows a list of individual SKUs affected by this PCN notice.

	AFFECTED PRODUCTS
Part Numbers	Description
CO-E1-11AA	COBOX MICRO DEVICE SERVER, ETHERNET
CO-E1-IAP-R	COBOX MICRO INDUSTRIAL PROTOCOL, RoHS
CO-E2-110AAR	COBOX MICTO W/THE TTL HEADER REMOVED, RoHS
CO-E2-113AAR	COBOX-MICRO, 2 SERIAL PORT SUPPORT & TTL HEADER ON BACK OF BOARD, RoHS
CO-E2-11AA	COBOX-MICRO WITH 2 SERIAL PORT SUPPORT
CO-E2-12AA-R	COBOX-MICRO W/NO LEDS, BUT INSTEAD, HEADER PINS ON THE TTL SIDE, ROHS
WP2001000-02	WIPORT, 2MB FLASH
LX100PEC1-02R	100 LQFP DSTNI-LX ASIC CHIP WITH PROFIBUS
LX1600EC1-02R	160 LQFP DSTNI-LX ASIC CHIP
LX160PEC1-02R	160 LQFP DSTNI-LX ASIC CHIP WITH PROFIBUS
LX1000000-02R	160 LQFP DSTNI-LX ASIC CHIP
LX180000B-02	180 PIN BGA MODEL OF THE DSTNI-LX ASIC CHIP WITH PROFIBUS PROTOCOL
LX180000B-02R	180 PIN BGA MODEL OF THE DSTNI-LX ASIC CHIP WITH PROFIBUS PROTOCOL, RoHS
LX2000000-02R	DSTNI-LX ASIC CHIP
EX1000000-01R	DSTNI-LX ASIC CHIP
MSSLITE-B2	MSSLITE WITH PIN HEADERS
MSSLITE-C	MSSLITE WITH SERIAL INTERFACE
MSSLITEX-C1	MSSLITE WITH EXTENDED MEMORY TO SUPPORT SDK & HTTP

NOTE: There are no planned direct replacements for these skus.

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

