

## PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an immediate change to the XPort Pro family of products. This change is part of our effort and commitment to continuous improvement of our products and processes.

### **Change Type**

Hardware

### **Products Affected**

| Part Number    | Description  | Old Revision | New Revision |
|----------------|--|--------------|--------------|
| XPP1003000-02R | XPort Pro Device Networking Module, Linux OS, 16MB SRAM, AES Encryption, Extended Temperature, RoHS, Bulk                      | B13          | B14          |
| XPP100300S-02R | XPort Pro Device Networking Module, Linux OS, 16MB SRAM, AES Encryption, Extended Temperature, RoHS, Sample                    | B13          | B14          |
| XPP1004000-02R | XPort Pro Lx6 Device Networking Module, Linux OS, IPv6 Enabled, 16MB SRAM, AES Encryption, Extended Temperature,, RoHS, Bulk   | D15          | D16          |
| XPP100400S-02R | XPort Pro Lx6 Device Networking Module, Linux OS, IPv6 Enabled, 16MB SRAM, AES Encryption, Extended Temperature,, RoHS, Sample | D15          | D16          |

### **Description and Extent of Change**

1. Thermal grease material changed from acrylic-based to resin-based compound
2. Connector changed from Panasonic to Molex
3. Enlarged PCB microvias

### **Reason for Change**

1. Appearance and performance enhancement
2. Component EOL
3. Enhance product robustness

### **Effect of Change on Fit, Form, or Function**

There is no impact to product fit, form, and function.

### **Effective Date of Change**

Affected products with the above changes will begin shipping from the factory immediately.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.