

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the XPress DR-IAP Industrial Device Server. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
XSDRIN-03	XPress DR-IAP Industrial Device Server with Installable Industrial Protocols, DIN Rail Mount, Serial Interface (RS-232/RS-422/RS-485 - terminal block or RJ45), 10Base-T/100Base-TX, 9-30VDC/9-24VAC, RoHS	A12	B12

Lantronix is pleased to announce the release of XPress DR-IAP standard tunneling firmware version 6.11.0.3 and Modbus firmware version 3.4.0.2.

Description and Extent of Change

- Resolves data transmission issue reported in RS485 2-wire mode
- The RS232/RS485 Select Switch (hardware) setting now has priority over the software setting

Reason for Change

- Some customers reported the inability of the XSDRIN-03 to receive data when connected to certain devices in RS485 2-wire mode
- Follows the RS232/RS485 switch setting priority used in the XSDRIN-02 product

For XSDRIN-03 customers that would like to take advantage of the new capabilities of IAP Standard Tunneling FW v6.11.0.3 and Modbus FW v3.4.0.2, the firmware and associated release notes are now available for download from our website: <http://www.lantronix.com/support/downloads.html>

Effect of Change on Fit, Form, or Function

Functional changes only as noted above.

Effective Date of Change

Affected product with firmware version 6.11.0.3 will begin shipping from the factory by June 15, 2016.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.