

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

This is to inform you that a change will be made to the following products.

Change Type

Software

Products Affected

Single AC Power Supply Models

Part Number	Description	Old Revision	New Revision
SLC80081201S	SLC 8000 Advanced Console Manager – 8 Ports RJ45, Single AC Power Supply	B13	C13
SLC80161201S	SLC 8000 Advanced Console Manager – 16 Ports RJ45, Single AC Power Supply	B13	C13
SLC80321201S	SLC 8000 Advanced Console Manager – 32 Ports RJ45, Single AC Power Supply	B13	C13
SLC80481201S	SLC 8000 Advanced Console Manager – 48 Ports RJ45, Single AC Power Supply	B13	C13
SLC81161201S	SLC 8000 Advanced Console Manager – 16 Ports USB, Single AC Power Supply	A11	B11
SLC82321201S	SLC 8000 Advanced Console Manager – 16 Ports RJ45, 16 Ports USB, Single AC Power Supply	A12	B12

Dual AC Power Supply Models

Part Number	Description	Old Revision	New Revision
SLC80082201S	SLC8000 Advanced Console Manager – 8 Ports RJ45, Dual AC Power Supply	B13	C13
SLC80162201S	SLC8000 Advanced Console Manager – 16 Ports RJ45, Dual AC Power Supply	B13	C13
SLC80322201S	SLC8000 Advanced Console Manager – 32 Ports RJ45, Dual AC Power Supply	B13	C13
SLC80482201S	SLC8000 Advanced Console Manager – 48 Ports RJ45, Dual AC Power Supply	B13	C13

Dual DC Power Supply Models

Part Number	Description	Old Revision	New Revision
SLC80162401S	SLC8000 Advanced Console Manager – 16 Ports RJ45, Dual DC Power Supply	B12	C12
SLC80322401S	SLC8000 Advanced Console Manager – 32 Ports RJ45, Dual DC Power Supply	B12	C12
SLC80482401S	SLC8000 Advanced Console Manager – 48 Ports RJ45, Dual DC Power Supply	B12	C12

Single AC Power Supply Models (TAA Compliant)

Part Number	Description	Old Revision	New Revision
SLC80081201G	SLC 8000 Advanced Console Manager – 8 Ports RJ45, Single AC Power Supply, TAA	B13	C13
SLC80161201G	SLC 8000 Advanced Console Manager – 16 Ports RJ45, Single AC Power Supply, TAA	B13	C13
SLC80321201G	SLC 8000 Advanced Console Manager – 32 Ports RJ45, Single AC Power Supply, TAA	B13	C13
SLC80481201G	SLC 8000 Advanced Console Manager – 48 Ports RJ45, Single AC Power Supply, TAA	B13	C13

Dual AC Power Supply Models (TAA Compliant)

Part Number	Description	Old Revision	New Revision
SLC80082201G	SLC8000 Advanced Console Manager – 8 Ports RJ45, Dual AC Power Supply, TAA	B13	C13
SLC80162201G	SLC8000 Advanced Console Manager – 16 Ports RJ45, Dual AC Power Supply, TAA	B13	C13
SLC80322201G	SLC8000 Advanced Console Manager – 32 Ports RJ45, Dual AC Power Supply, TAA	B13	C13
SLC80482201G	SLC8000 Advanced Console Manager – 48 Ports RJ45, Dual AC Power Supply, TAA	B13	C13

Lantronix is pleased to announce the release of new and improved SLC 8000 firmware 7.3.0.0R11.

Description and Extent of Change

The release includes new features and bug fixes including:

- Zero Touch Provisioning
- Expanded IPv6 Support
- Remote Power Management support for PDU's and UPS's from 140 different vendors
- Non-Java-based WebSSH and WebTelnet applications
- Device Port Token Monitoring

Reason for Change

New features and expanded capabilities

For SLC8000 customers that would like to take advantage of the above new capabilities, the firmware and associated release notes are now available for download from our website:

<http://www.lantronix.com/products/lantronix-slc-8000/#tab-docs-downloads>

More information about SLC 8000 *Advanced Console* Manager is available on our website:

<http://www.lantronix.com/products/lantronix-slc-8000/>

Effect of Change on Fit, Form, or Function

Functional changes only as noted above.

Effective Date of Change

Affected products with firmware 7.3.0.0R11 will begin shipping from the factory on July 15, 2016.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.